

BMW / E83 / WBAPD91090WG40260 / TS:grey

TeleServices calls

Vehicle identification

Order base and inspection

Vehicle key data

Central vehicle data

Central data

Maintenance history

Repair history

Technical campaigns

Service contracts

TeleServices data

Vehicle data

Options / retrofits

Individual data

Control units

Vehicle data

VIN	WBAPD91090WG40260
Lead model	PD01
Model	PD01
Model designation	X3 3.0D
Series	E83
Colour	475 - black-sapphire metallic
Upholstery	KCSW - Sensatec/black
Engine type	M57/T2
Gearbox no.	4080410
Engine no.	23506566
Date of manufacture	2007-06-01
Last identified mileage	134,074 Kilometres

BMW / E83 / WBAPD91090WG40260 / TS:grey

[TeleServices calls](#)[Vehicle identification](#)[Order base and inspection](#)[Vehicle key data](#)[Central vehicle data](#)[Central data](#)[Maintenance history](#)[Repair history](#)[Technical campaigns](#)[Service contracts](#)[TeleServices data](#)

<u>Completion date</u>	<u>Kilometre reading</u>	<u>Dealer no.</u>	<u>Type</u>	<u>Total FRUs</u>	<u>Warranty</u>	<u>Dealer</u>	<u>Customer</u>	<u>SI</u>
<u>25-07-2008</u>	120,124 Kilometres	04107	D	19	☐	☐	☒	☐
<u>14-05-2008</u>	97,179 Kilometres	30631	D	0	☐	☐	☐	☒
<u>07-04-2008</u>	84,952 Kilometres	30631	D	0	☐	☐	☐	☒
<u>19-03-2008</u>	82,463 Kilometres	30631	D	0	☐	☐	☐	☒
<u>23-01-2008</u>	64,600 Kilometres	30631	D	0	☐	☐	☐	☒
<u>24-10-2007</u>	38,608 Kilometres	30631	D	9	☐	☐	☐	☒

BMW / E83 / WBAPD91090WG40260 / TS:grey

Details of the entry of the repair history

Item Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
1 64 31 9 071 935	MICROFILTER/ACTIVATED CARBON CONTAINER	1	☐	☐	☐
1 11 42 7 788 460	Set oil-filter element	1	☐	☐	☐
1 00 00 901	FRU specification for shop-internal labour invoicing	0	☐	☐	☐
1 00 00 250	BMW engine oil service incl. additional service	0	☐	☐	☐
2 61 61 0 409 727	Set of wiper blades	1	☐	☐	☐
2 61 62 3 400 709	WIPER BLADE	1	☐	☐	☐
3	Rotary latch lock/system lock, front Sticking/jammed		☐	☐	☐
3 51 21 7 167 071	Door lock left	1	☐	☐	☐
3 51 48 3 334 923	SOUND INSULATING DOOR FRONT LEFT	1	☐	☐	☐
3 51 21 590	Removing and installing or replacing lock of left or right front door	9	☐	☐	☐

Roadside Assistance

Close

BMW / E83 / WBAPD91090WG40260 / TS:grey

Details of the entry of the repair history

Item Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
1 64 31 9 071 935	MICROFILTER/ACTIVATED CARBON CONTAINER	1	☐	☐	☐
1 11 42 7 788 460	Set oil-filter element	1	☐	☐	☐
1 00 00 900	FRU specification for shop-internal labour invoicing	0	☐	☐	☐
1 00 00 221	BMW Inspection I including body inspection and old oil disposal	0	☐	☐	☐
2 34 35 3 411 756	Brake pad wear sensor	1	☐	☐	☐
2 34 11 3 400 151	Brake disc, ventilated	2	☐	☐	☐
2 34 11 3 404 362	Repair kit, brake pads asbestos-free	1	☐	☐	☐
2 34 11 609	Removing and installing or replacing both front brake discs	0	☐	☐	☐
3 34 21 3 332 217	Brake disc, ventilated	2	☐	☐	☐
3 34 21 3 403 241	Repair kit, brake pads asbestos-free	1	☐	☐	☐
3 34 35 3 411 757	Brake pad wear sensor	1	☐	☐	☐
3 34 21 928	Removing and installing or replacing both rear brake discs	0	☐	☐	☐
4 34 41 0 304 483	Repair kit springs	1	☐	☐	☐
4 34 41 6 761 293	Repair kit brake shoe asbestos-free	1	☐	☐	☐
4 34 41 660	Removing and installing or replacing all parking brake shoes	0	☐	☐	☐
5 61 62 3 428 599	WIPER BLADE	1	☐	☐	☐
5 61 61 0 409 727	Set of wiper blades	1	☐	☐	☐
6 00 12 995	Vehicle care BSP (CH)	0	☐	☐	☐
7 13 71 3 428 558	Air filter element	1	☐	☐	☐
7 13 72 501	Replacing air filter cartridge	0	☐	☐	☐

Roadside Assistance

Close

BMW / E83 / WBAPD91090WG40260 / TS:grey

Details of the entry of the repair history

Item	Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
1	61 62 3 400 709	WIPER BLADE	1	☐	☐	☐
1	61 61 0 409 727	Set of wiper blades	1	☐	☐	☐

Roadside Assistance

Close

BMW / E83 / WBAPD91090WG40260 / TS:grey

Details of the entry of the repair history

Item	Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
1	63 21 7 160 780	BULB	1	☐	☐	☐
		Replacing halogen				
1	63 99 072	light bulb for left low beam headlight	0	☐	☐	☐

Roadside Assistance

Close

Details of the entry of the repair history

Item	Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
1	64 31 9 071 935	MICROFILTER/ACTIVATED CARBON CONTAINER	1	☐	☐	☐
1	11 42 7 788 460	Set oil-filter element	1	☐	☐	☐
1	13 32 7 788 700	Fuel filter cartridge	1	☐	☐	☐
1	00 00 901	FRU specification for shop-internal labour invoicing	0	☐	☐	☐
1	00 00 525	Additional work during every 3rd engine oil change	0	☐	☐	☐
1	00 00 250	BMW engine oil service incl. additional service	0	☐	☐	☐
2	00 12 995	Vehicle care BSP (CH)	0	☐	☐	☐
3	63 21 7 160 780	BULB	2	☐	☐	☐
3	63 99 091	Replacing halogen light bulbs for both low beam headlights	0	☐	☐	☐
3	63 99 575	Replacing halogen light bulbs for both low beam headlights	0	☐	☐	☐

Roadside Assistance

BMW / E83 / WBAPD91090WG40260 / TS:grey

Details of the entry of the repair history

Item Number	Description	Quantity	Local	Original/qualified customer statement	Qualified workshop statement
101 34 11 010	Replacing brake pads of front and rear disc brakes	14	☐	☐	☐
101 34 11 3 400 151	Brake disc, ventilated	2	☐	☐	☐
101 34 11 3 404 362	Repair kit, brake pads asbestos-free	1	☐	☐	☐
101 34 11 6 750 159	Clip	2	☐	☐	☐
101 34 21 1 161 806	Inner hex bolt	2	☐	☐	☐
101 34 21 3 403 241	Repair kit, brake pads asbestos-free	1	☐	☐	☐
101 34 21 6 753 675	Clip	2	☐	☐	☐
101 34 35 3 411 756	Brake pad wear sensor	1	☐	☐	☐
101 34 35 3 411 757	Brake pad wear sensor	1	☐	☐	☐
102 9999999	Interne Rep.-Wäsche (von Fa.GAP durchgeführt)	0	☒	☐	☐
103 AZ33333	Füllstände prüfen ggf. erg {nzen Frostschutz JA/NEINScheibenreiniger JA/NEIN Motor JA/NEIN	0	☒	☐	☐
104 00 52 051	Quick service and service ticket with compact check or service consultation	1	☐	☐	☐
105 34 11 613	Removing and installing or replacing both front brake discs	2	☐	☐	☐
106 34 35 512	Replacing both brake pad sensors	2	☐	☐	☐

Roadside Assistance

Close